

800-330-3867 Option 3 www.MesaSupplies.com

Instructions For Dark Garment Laser Transfer Paper



RECOMMENDATIONS

Fabric Color	Hot Peel	Warm Peel	Cold Peel	Hand Iron
Dark			1	×

COMMERCIAL PRESS INSTRUCTIONS

PRINTING INSTRUCTIONS:

- 1. Print the image in reversed/mirrored format onto the 'Imaging Sheet' (Purple backing paper).
 - a. Typical printer setting is 'heavy'.

PRE-TRANSFERRING INSTRUCTIONS:

1. Prepare the substrate by ensuring the surface is clean, dry and wrinkle free.


TRANSFERRING INSTRUCTIONS:

Step 1:


- 1. Place the printed Imaging Sheet to the Transfer Sheet (Brown backing paper) on the heat press. Place Kraft Paper on top of the sheet
 - a. Press two sheets against each other so backing papers are facing out.
- 2. Press 20 seconds @ 250°F* using medium/heavy pressure.
- 3. Peel the papers apart while still **hot** in a smooth, quick, even motion.

Step 2:

- 1. Place garment onto heat press.
- 2. Press the treated Sheet face down onto the shirt or substrate with Kraft Paper on top
- 3. Press 35 seconds @ 375°F* using heavy pressure.
- 4. Peel the paper once **cold** in a smooth, guick, even motion.
- 5. For a softer feel to the transferred image, after you peel it from the t-shirt stretch it (side to side then top to bottom), then cover with kraft paper and press another 20 seconds



Imaging Sheet



Transfer Sheet

*The following temperatures/times are for STAHLS brand heat presses for other brands you may need to adjust temperature up or down

Watch YouTube Instructional Video at: http://www.uprintamerica.com/uprint_video.asp

WASHING INSTRUCTIONS: Turn garment inside out and wash in cold water using a mild detergent. Do not use bleach. Dry on low-heat setting. Do not iron directly on the transferred area. **IMPORTANT:** Heat presses vary in accuracy. The sellers and manufactures maximum obligation shall be to replace any paper that has proven to be defective.